


# 9 TRI TR76DOLL SII

- Ultra-Fast 3D Inline AXI
- Precise 3D CT Imaging
- Rapid Intelligent Programming
- Extra Large Board Inspection
- Automated Defect Evaluation


AUTOMATED
X-RAY INSPECTION

# TR7600LL SII/TR7600M SII


# Defect Symptom Images




BGA Head-In-Pillow



**BGA Void** 




Bridging



38080

PressFit Pin Defect




# Inline 3D Automated X-ray CT Inspection

- Ultra fast inline automated X-ray inspection of PCBAs
- 2D + 3D images using multiple angled cameras
- Automated inspection and pass/fail evaluation
- User selectable X-ray power up to 130 kV/300 μA
- Patented 6-axis motion control for maximum flexibility
- Edge-to-edge large board inspection up to 1000 x 660 mm
- Advanced 3D CT capability for vertical slicing of complex solder joints

# Intelligent Software Solution


- Intelligent detection of solder and assembly defects
- Automatic image quality enhancement for overlapping components and complex defects
- Automatic board warp compensation
- Automated 3D slice extraction

# **Defect Detection Capability**




#### Patented 6-axis Motion Control

TRI's unique motion control system provides clearest images of multi-layer PCBAs and overlapping components, enabling reliable automated inspection of dual-side PCB assemblies without typical shadowing issues.



# BlockScan Customized Imaging

BlockScan module enhances AXI test program coverage by re-scanning selected areas of the tested board using customized system settings. This improves image quality and automated defect detection for most complex PCBAs, including fine pitch µBGAs, PressFit and metal shielded components. Using BlockScan, TRI AXI can reliably inspect up to 3-layer PoP packages.



# 3D CT Inspection Optional Upgrade


Enhanced 3D inspection with planar CT imaging can recreate a complete 3D model of each solder joint, enabling clear analysis of shape irregularities, head-in-pillow and voiding problems. Vertical cross-section CT images help with reliable visual review of borderline and buried solder joints.



#### Enhanced Defect Visualization with CT

CT data processing helps clearly visualize solder defects such as voiding, bridging and deformities.





3D CT displays solder joints and defects in much more detail than traditional 3D X-ray slicing

# Eliminate Board Warp Issues

The TR7600LL SII and TR7600M SII use multiple laser sensors to accurately measure any PCB assembly deformation and automatically adjusts component inspection parameters to compensate for local board warpage. This ensures reliable inspection of the most complex boards with overlapping and multi-layered components and heavy PressFit connectors.

#### Radiation Safe Design

Designed with safety in mind, TRI's AXI systems have full lead shielding which prevents harmful exposure in everyday use and reduces X-ray leakage below background radiation levels of 0.5  $\mu$ Sv/hr. The certified safety design conforms to USFDA Code of Federal Regulations Title 21, Part 1020.40.


#### Repair Station

The TR7600LL SII and TR7600M SII collect a wide range of inspection data to offer instantaneous process monitoring and analysis. This integrated approach offers clear statistical feedback that improves defect management and enhances the efficiency of the inspection process.




# **Industry 4.0 Production Line Integration**

YMS 4.0 lets TRI inspection solutions interface and share inspection data with the shop floor system and other inspection machines. With the central console an operator can control, track, analyze and optimize the inspection process across the entire production line and obtain real actionable data to optimize production quality in the Industry 4.0 environment.



# Yield Management System



- Inspection results and data integration
- Real time SPC and production yield management
- Quality reports and closed loop tracking
- Support defect component analysis and improvements
- Knowledge Management (KM)
- Productivity and Quality Management

# Test Research, Inc.

#### Headquarters

7F., No.45, Dexing West Rd., Shilin Dist., Taipei City 11158, Taiwan TEL: +886-2-2832-8918 FAX: +886-2-2831-0567

FAX: +886-2-2831-0567 E-Mail: sales@tri.com.tw http://www.tri.com.tw

#### Linkou, Taiwan

No.256, Huaya 2nd Rd., Guishan Dist., Taoyuan City 33383, Taiwan TEL: +886-2-2832-8918 FAX: +886-3-328-6579

#### Hsinchu, Taiwan

7F., No.47, Guangming 6th Rd., Zhubei City, Hsinchu County 30268, Taiwan TEL: +886-2-2832-8918 FAX: +886-3-553-9786

#### Shenzhen, China

5F.3, Guangxia Rd., Shang-mei-lin Area, Fu-Tian Dist., Shenzhen, Guangdong, 518049, China TEL: +86-755-83112668 FAX: +86-755-83108177 E-mail: shenzhen@cn.tri.com.tw

#### Suzhou, China

B Unit, Building 4, 78 Xinglin St., Suzhou Industrial Park, 215123, China TEL: +86-512-68250001 FAX: +86-512-68096639 E-mail: suzhou@cn.tri.com.tw

# Shanghai, China

Room 6C, Building 14, 470 Guiping Rd., Xuhui Dist., Shanghai, 200233, China TEL: +86-21-54270101 FAX: +86-21-64957923 E-mail: shanghai@cn.tri.com.tw

# USA

832 Jury Court, Suite 4, San Jose, CA 95112 U.S.A TEL: +1-408-567-9898 FAX: +1-408-567-9288 E-mail: triusa@tri.com.tw

#### Europe

O'Brien Strasse 14 91126 Schwabach Germany TEL: +49-9122-631-2127

FAX: +49-9122-631-2147 E-mail: trieurope@tri.com.tw

> 2-9-9 Midori, Sumida-ku, Tokyo, 130-0021 Japan TEL: +81-3-6273-0518 FAX: +81-3-6273-0519 E-mail: trijp@tri.com.tw

#### Korea

No.207 Daewoo-Technopia, 768-1 Wonsi-Dong, Danwon-Gu, Ansan City, Gyeonggi-Do, Korea TEL: +82-31-470-8859 FAX: +82-31-470-8859 E-mail: trikr@tri.com.tw

#### Malaysia

C11-1, Ground Floor, Lorong Bayan Indah 3 Bay Avenue, 11900 Bayan Lepas Penang, Malaysia

TEL: +604-6461171 E-mail: trimy@tri.com.tw

# X-Ray & Imaging System

X-ray Source 130 kV max (user adjustable)
Image Resolutions 7 μm,10 μm,15 μm or 10 μm,15 μm, 20 μm (factory setting)
Camera High-performance, ultra-sensitive line-scan cameras

# Inspection Functions

Component Level Defects Missing, Misalignment, Tombstone, Billboard, Tantalum Polarity, Rotation, Floating

Joint Level Defects Insufficient/Excess Solder, Bridging, Open, Solder Ball, Non-wetting, Void & Lifted Lead

#### X-Y Table & Control

High-precision ball screw/servo motor with DSP-based motion controller


X-Y Axis Resolution 1 μm


# PCB & Conveyor System

		TR7600M SII	TR7600LL SII	
Min. PCB Size		50 x 50 mm (1.97 x 1.97 in.)		
Max. PCB Size		700 x 350 mm (27.6 x 13.8 in.)	1000 x 660 mm (39.3 x 26.0 in.)	
PCB Thickness		0.6 - 5 mm	0.6 - 7 mm	
PCB Transport Height		880 - 920 mm (34.6 - 36.2 in.)*		
Max. PCB Weight		3 kg (7 lbs) [8 kg (18 lbs) optional]	12 kg (26 lbs) [15 kg (33 lbs) optional]	
PCB Carrier/Fixing		Step motor driven conveyor & pneumatic clamping		
Clearance				
Тор	20 µm	50 mm	(1.97 in.)	
	15 µm	30 mm (1.18 in.)		
	10 µm	15 mm (0.59 in.)		
	7 μm	7 mm (0.28 in.)		
Bottom		70 mm (2.75 in.)		
Edge		3 mm (0.11 in.) [5 mm (0.20 in.) optional]		

<sup>\*</sup> SMEMA Compatible

# **Dimensions**





Unit: mm (in.)

	TR7600M SII	TR7600LL SII
Weight	3375 kg (7441 lbs)	4500 kg (9920 lbs)
Power Requirement	200 - 240 VAC single phase, 50/60 Hz, 4 kVA	200 - 240 VAC three phase, 50/60 Hz, 7 kVA (346-416 VAC optional three phase transformer)
Air Requirement	Requirement 72 psi - 87 psi (5 - 6 bar)	

## Optional Accessories

Barcode Scanner, Repair Station, Offline Editor & Yield Management System (YMS 4.0), YMS Lite, 3D CT Upgrade Kit

TRI has a patent in System and Method for Laminography Inspection

Specifications are subject to change without notice. Content may not be used as acceptance criteria. All trademarks are the property of their owners.

# 『RI " 德律" TRI INNOVATION "

The absence of a product or service name or logo from this list does not constitute a waiver of TRI's trademark or other intellectual property rights concerning that name or logo. All other trademarks and trade names are the property of their owners.

